



Hot Key	Short Description	Full Description
ALT-A	ALN	Alignment
ALT-B	BR	Bridge
ALT-C	SIG	Signal/Comms.
ALT-D	DE	Drag Equip. Detect
ALT-E	EB	Engine Burn
ALT-F	FX	Farm/Pvt. Grd Xing
ALT-G	GX	Grade Xing
ALT-H	ST	Station/Stop
ALT-I	CV	Curve
ALT-J	SP	Spiral
ALT-K	K	Kink
ALT-L	XL	Cross Level
ALT-M	-	Auto-Memo Open
ALT-N	NT	Change Track/Owner
ALT-O	OT	Open Track
ALT-P	PUB	Pub Grd Xing
ALT-Q	G	Gage
ALT-R	CLS	Change Track Class
ALT-S	SW	Switch
ALT-T	TO	Turnout
ALT-U	TUN	Tunnel
ALT-V	PF	Profile
ALT-W	WP	Warp
ALT-X	XO	Crossover
ALT-Y	YD	Yard
ALT-Z	MUD	Fouled Ballast